Release Notes

Release Note:	**Memor™ 12_17_30_35 Android™ 15 Version 3.27.022**	**Distribution Date:**	October 16, 2026
Product Involved:	Memor™ 12 - Memor™ 17 - Memor™ 30 - Memor™ 35		
Description:	**Memor™ 12_17_30_35 Android™ 15 Version 3.27.022 Firmware Release**		
Business Unit:	Mobile Computers		

Distribution Scope: ☐ **Internal** ☒ **External – specify:** **Public**

Memor™ 12_17_30_35 Android™ 15 version 3.27.022.20261006s

1. COMPATIBILITY

- **Memor™ 12 GMS**
- **Memor™ 17 GMS**
- **Memor™ 30-30X GMS**
- **Memor™ 35-35X GMS EMEA+ROW**
- **Memor™ 35-35X GMS NA**

Memor™ 12-17 and Memor™ 30-30X-35-35X Android™ 15 firmware version downgrade to any Android™ 13 firmware versions is ALLOWED(*) (forcing factory reset).

Memor™ 12-17 and Memor™ 30-30X-35-35X Android™ 13 firmware version upgrade to any Android™ 15 firmware versions is ALLOWED(*).

(*)Downgrading the firmware version may be subject to planned obsolescence of hardware components.

To check the firmware version, go to Settings>About phone and read the Build number.

To check the Android version, go to Settings>About phone and read the Android version.

IMEI1 and IMEI2 information may be swapped compared from that on the WWAN device label.

2. ENHANCEMENTS

2.1. Security Enhancements

a. Updated Android security patches level at September, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-09-01].

2.2. Miscellaneous Enhancements

a. Updated DL Scanner service to 3.2.0.0-r1.1 version including:
    a. Support for the following scan engine variants (239290)
        i. "*XenonXLR*"
        ii. "*XenonXLRColor*"
        iii. "*ArgonColor*"
        iv. "*ArgonRiskExempt*"
b. Updated SDK add-on to 1.50.4 version.
c. Updated DL Services to 1.50.3 version.
d. Added signature permissions for TeamViewer Datalogic Add-On solution in Android signature permissions allowlist. (239636)

3. CORRECTED DEFECTS

3.1. None

4. KNOWN LIMITATIONS

4.1. Phone

a. A reboot notification is displayed after each reboot with an active eSIM in the device. (208994)
b. Preferred subscriptions for calls and messages are incorrectly reported in dual SIM settings. (207764)
c. 5G SA (standalone) functionality for Verizon is not available. (207209) [Memor 35]
d. DL SDK usage of *DualSimStatus* fails when eSIM is present on device preventing to set SMS/Call/Data preference when using Scan2Deploy Studio or MDMs. (193636)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

e. Preference setup for eSIM may not take effect enrolling with Scan2Deploy Studio or MDMs if a physical SIM is already inserted into the device. (193586) Workaround: Re-apply profile settings.

4.2. Desktop Mode

a. *External screen app on insert* setting does not work in dual screen mode. (208189)
b. Taskbar icons do not have any effect if pressed when configuring DL Launcher. (195654)
c. If Single Screen desktop mode is active, then it prevents the orientation from being fixed in portrait when the device is docked. (194353)
d. The Camera app is rotated 90 degrees in the secondary display. (192402)
e. Unable to search for apps in the Dual Screen desktop mode menu while an app is open. (186822)

4.3. Miscellaneous

a. Wi-Fi user certificates may be lost upon reboot if they are installed via EMMs. (236657, 237671) Workaround: Install Wi-Fi user certificates manually.
b. In very rare cases, when you turn on the device using one of the side scan buttons, the display backlight may not work. (229464) [Memor 1X] Workaround: reboot device.
c. During the installation of updated DL resources from the Espresso extension, the message "*Google Play Protect - Recommended app scan*" may appear. (207678)
d. The virtual keyboard input method does not change accordingly when Gboard and Google Voice Typing settings are changed. (205682)
e. Conditional factory reset could occur by upgrading from an Android 13 version with a newer build date.

5. FILES

- memor1x_3x_js_gms-user-ota-3.27.022.20261006s.zip [Memor™ 12_17_30_35 Android™ 15 GMS 3.27.022]
- ReleaseNotes_Memor 12_17_30_35-Android 15-v3.27.022.pdf [this document]

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

6. OTHER NOTES

Android Security:

- Android security update September 5, 2026

Other Dependencies:

- Scan2Deploy Studio 2.6.2 or newer
- Datalogic Android SDK 1.50
- Espresso Extension 3.27.003

Upgrade methods:

- Scan2Deploy Studio: see the specific *Scan2Deploy* section available in the *Memor™ 12_17_30_35 user manual*.
- Memor™ 12_17_30_35: installing OTA locally via *System Update* option available in *Settings>System Update*.
- SDK intent
- ADB sideload

7. SUPPORT

Datalogic Download area:

Memor 12_17 - Android - Products - Datalogic Developer Portal

Memor 30_35 - Android - Products - Datalogic Developer Portal

Datalogic Support & Service:

Support and Service - Datalogic

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

8. HISTORY

Memor™ 12_17_30_35 Android™ 15 version 3.27.018.20260727s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at August, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-08-01].

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue with the interaction between the charging subsystem and the GPS functionality that could prevent the device from charging properly when placed in the cradle or connected via USB. (232882) [Memor 17 – Memor 35]

Memor™ 12_17_30_35 Android™ 15 version 3.27.017.20260721s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at July, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-07-01].

Desktop Mode Enhancements

- Improvements to the window management experience in Desktop Mode, with visual and interactive optimizations related to the caption bar, window corners, and resizing behaviour. (231486)

Miscellaneous Enhancements

- Updated SDK add-on to 1.50.3 version.
- Updated DL Services to 1.50.2 version.
- Updated DL Resources to 1.50.4 version.
- Updated SetupWizardScanner to 1.44.0 version.

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated DL Settings to 2.29.1 version.
- Updated Battery Manager to 2.19.2 version.
- Updated Dock Manager to 1.32.0 version.
- Added signature permissions for the MDM solution *TinyMDM* to the Android signature permissions allowlist. (226402)
- Added signature permissions for *MCL* enterprise mobility solution in Android signature permissions allowlist. (228951)
- All supported charging dock properties have been added to the list of properties supported by the SDK. (230678)

CORRECTED DEFECTS

Wi-Fi Corrections

- Fixed an issue where, in some cases, the device was unable to automatically reconnect to the Wi-Fi network after a restart when there was no Internet connection. (231985)

Desktop Mode Corrections

- Fixed an issue where the screensaver, when enabled, did not appear on the external display. (230338)
- An issue has been resolved in which, in some cases, the lock screen on the external display might no longer show the unlock option after suspend-resume sequence. (230468)
- Fixed an issue where, in Dual Screen mode, the secondary screen could sometimes display the main screen. (231824)
- Fixed an issue where, in Dual Screen mode, the taskbar was not hidden on the lock screen. (231841)

Miscellaneous Corrections

- Correct the signature permissions for *BlueFletch* software suite in Android signature permissions allowlist.
- An issue has been resolved in which the "*uninstall_blocked_packages*" restriction applied to apps installed via Espresso did not prevent the entire uninstallation of those apps via ADB or when attempting to uninstall their updates. (228845, 228846)
- Fixed an issue where *Datalogic settings* could crash if you opened a submenu, then minimized the app, and then reopened it. (231689)
- Fixed an issue where the time displayed on the lock screen was clipped upon resuming when displayed in French format. (231784)
- Fixed a functional issue with the Expedite Setup MDM enrollment feature. (233526)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Memor™ 12_17_30_35 Android™ 15 version 3.27.015.20260611s

Firmware version not publicly released

Memor™ 12_17_30_35 Android™ 15 version 3.27.009.20260508s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at June, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-06-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.2.0.0-r1 version including:
  a. Added support to Laetus Pharmacode. (218059)
- Updated SDK add-on to 1.50.2 version.
- Updated DL Services to 1.50.1 version.
- Updated DL Resources to 1.50.2 version.
- Updated DevicePolicyManager to 5.7.0 version.
- Updated DL Settings to 2.29.0 version.
- Updated Battery Manager to 2.19.1 version.

CORRECTED DEFECTS

Wi-Fi Corrections

- Fixed an issue where, on some types of Meraki AP, the device might not support connections to hidden SSIDs. (229200)

Memor™ 12_17_30_35 Android™ 15 version 3.27.008.20260414s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at May, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-05-01].

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Desktop Mode Enhancements

- Now the lock screen for the DL secondary display is shown on the display only if Android VIRTUAL_DISPLAY_FLAG_SECURE has been enabled. (224570)

Phone Enhancements

- Added support to 5G SA (standalone) functionality for T-Mobile. (224519) [Memor 17]
- Added support to 5G network type for Qatar Mobile Country Code. (217770) [Memor 35]

Miscellaneous Enhancements

- Updated SDK add-on to 1.50.0 version.
- Updated DL Services to 1.50.0 version.
- Updated DL Resources to 1.50.0 version.
- Updated SetupWizardScanner to 1.43.0 version.
- Updated DL Settings to 2.28.3 version.
- Updated Battery Manager to 2.19.0 version.
- Updated Dock Manager to 1.31.0 version.
- Updated DL Extension (UX Settings) to 0.15.0 version.
- Introduced ITF-14 as GTIN format for scanner formatting.
- Introduced conversion options from GS1-128.
- Introduced the ability to adjust the illumination intensity of Xenon and Argon scanner module.
- Introduced NFC group settings in DL Settings. (226376)
- Introduced Bluetooth Fast Pair option for fast pair compatible BT devices. (227251)
- Integrated automated I2C recovery mechanism specifically for backlight, battery, and NFC subsystems. (228712)

CORRECTED DEFECTS

Phone Corrections

- Fixed an issue where 5G connectivity was disabled for all countries, not just Vietnam. (229579) [Memor 17]

Miscellaneous Corrections

- Several general issues related to battery swap have been resolved. (219084, 222002, 225158, 225256, 225268, 228143, 228144) [Memor 1X]

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Memor™ 12_17_30_35 Android™ 15 version 3.22.008.20260318s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at April, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-04-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.1-r2 version.
- Updated SDK add-on to 1.49.2 version.
- Updated DL Services to 1.49.3 version.
- Updated DL Resources to 1.49.2 version.
- Updated DL Settings to 2.28.2 version.
- Updated DL Extension (UX Settings) to 0.14.3 version.
- Added signature permissions for BlueFletch software suite to the Android signature permissions allowlist. (225416)

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed potential issues with slow applications performance caused by the GPU driver. (218512)
- Fixed an issue that prevented Bluetooth silent pairing from working properly for both trusted and whitelisted devices. (226007, 223938)
- Fixed an issue with the "*Restrict access*" option that did not prevent access to the device settings. (226331)
- Fixed an issue that, in rare cases after device startup, caused the Battery Manager to report an incorrect battery temperature value. (227444)

Memor™ 12_17_30_35 Android™ 15 version 3.22.001.20260211s

ENHANCEMENTS

Security Enhancements

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated Android security patches level at March, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-03-01].

Wi-Fi Enhancements

- Introduced Wi-Fi 6E support for Vietnam. (223812) [Memor 1X]

Desktop Mode Enhancements

- Introduced screenshot capture support for secondary display in dual screen mode. (191734)
- Introduced lock screen support for secondary display in dual screen mode. (217265)

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r9 version.
- Updated SDK add-on to 1.49.0 version.
- Updated DL Services to 1.49.0 version.
- Updated DL Resources to 1.49.0 version.
- Updated SetupWizardScanner to 1.42.1 version.
- Updated DL Settings to 2.28.0 version.
- Updated Scan2Deploy Agent to 2.8.0 version.
- Updated Battery Manager to 2.18.0 version.
- Updated DL Extension (UX Settings) to 0.14.2 version.
- Disabled hint to extend battery life.
- Added modem reset option in Android recovery menu. (222665)
- Introduced automatic WLAN recovery procedure in case of WLAN subsystem crash. (223219)
- Added signature permissions for the MDM solutions SureMDM, Esper, and Omnissa (also known as AirWatch) to the Android signature permissions allowlist. (224544)

CORRECTED DEFECTS

Phone Corrections

- Fixed an issue where, under certain specific circumstances, the modem could freeze, causing the phone to become unstable. (223220) [Memor 35]

Miscellaneous Corrections

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Fixed an issue caused by the display size not being defined at system level, which in some specific cases could cause apps to be oriented incorrectly. (225201) [Memor 1X]
- Fixed an issue that prevented the device from booting after disabling the Settings app. (195605, 223139)

Memor™ 12_17_30_35 Android™ 15 version 3.16.008.20251216s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at January, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-01-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r6 version including:
  a. Added the ability to send an IME action (virtual keyboard function) at the end of the scanned code in keyboard wedge mode (215174)
- Updated SDK add-on to 1.47.8 version.
- Updated DL Services to 1.47.6 version.
- Updated DL Resources to 1.47.7 version.
- Updated SetupWizardScanner to 1.40.3 version.
- Updated DL Settings to 2.26.5 version.
- Updated Battery Manager to 2.17.3 version.
- Updated DL Extension (UX Settings) to 0.13.0 version.

CORRECTED DEFECTS

Miscellaneous Corrections

- Removed 5G network type for Vietnam Mobile Country Code. (218539) [Memor 17]
- Fixed an issue that made it impossible to decrypt Scan2Deploy V3 barcodes after completing the setup process from the “Hi There” screen. (219513)

Memor™ 12_17_30_35 Android™ 15 version 3.16.004.20251124s

ENHANCEMENTS

Security Enhancements

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated Android security patches level at November, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-11-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r2 version including:
  a. Always On status maintained at reboot when pin or password are set as lock screen
  b. Added alignment of the scanner camera id to the one specified in the firmware
- Updated SDK add-on to 1.46.14 version.
- Updated DL Services to 1.46.14 version.
- Updated DL Resources to 1.47.3 version.
- Updated SetupWizardScanner to 1.41.0 version.
- Updated DL Settings to 2.26.1 version including display brightness range setting.
- Updated Battery Manager to 2.17.0 version.

CORRECTED DEFECTS

Desktop Mode Corrections

- Fixed an issue that prevented DL Launcher from supporting Dual Screen mode. (186828, 190178)

Miscellaneous Corrections

- Fixed an issue that prevented the scanner from functioning correctly in the event of a camera failure. (218768)
- Fixed an issue that disabled mobile data roaming enabled via EMM through OEMConfig after restarting. (216877)

Memor™ 12_17_30_35 Android™ 15 version 3.12.006.20250924s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at September, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-09-01].

Miscellaneous Enhancements

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated DL Scanner service to 3.1.1.0-r1 version including:
    a. Add always on property and manage the preview when no barcode is shown for camera wedge
    b. Do not allow setting scan mode to always on with scanner disabled
    c. Add OCR correction for check digit evaluation (215181)
- Updated SDK add-on to 1.46.13 version.
- Updated DL Services to 1.46.13 version.
- Updated DL Resources to 1.46.7 version.
- Updated SetupWizardScanner to 1.40.3 version.
- Updated DevicePolicyManager to 5.6.0 version.
- Updated DL Settings to 2.25.3 version.
- Updated Scan2Deploy Agent to 2.7.0 version.
- Updated PackageInstaller to 7.8.0 version.
- Updated Battery Manager to 2.16.4 version.
- Updated DL Scan Demo to 1.5.0 version.
- Increased Android virtual memory heap values allocated for an app from 128 MB/256 MB to 256 MB/512 MB. In some application circumstances, this may prevent potential slowdowns and out of memory errors. (208718)

CORRECTED DEFECTS

Desktop Mode Corrections

- Fixed a graphical issue that occurred in Dual Screen mode after resizing an application and displaying it as freeform window in full screen. (209287)
- Fixed an issue that could cause a graphical glitch when moving an application in freeform mode from the secondary screen to the primary screen. (205564, 209277)
- Fixed an issue that sometimes caused a window to remain fixed on the left side of the secondary screen when moving an application from the primary screen to the secondary screen. (207456)

Miscellaneous Corrections

- Fixed an issue that caused the device to automatically disconnect from USB debugging when the USB function was switched to MTP, PTP or MIDI mode. (211562)
- *Walkie-Talkie Application* option is now available in *Push to talk* settings. (208091)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Memor™ 30_35 Android™ 15 version 3.03.005.20250616

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at June, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-06-01].

Miscellaneous Enhancements

- OS Android updated to version 15.
- Introduced battery optimizations settings.
- Updated SDK add-on to 2.1 version.
- Updated DL Scanner service to 2.2.0.45-r3 version.
- Updated SetupWizardScanner to 2.1.3 version.
- Updated DL Settings to 3.1.1 version.
- Updated Scan2Deploy Agent to 2.6.2 version.
- Updated PackageInstaller to 8.0.2 version.
- Updated Battery Manager to 3.0.0 version.

CORRECTED DEFECTS

None

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.