# Release Notes

| | | | |
|---|---|---|---|
| **Release Note:** | **Joya™ Smart_Smart+ Android™ 15 Version 3.27.022** | **Distribution Date:** | October 16, 2026 |
| **Product Involved:** | Joya™ Smart – Joya™ Smart+ | | |
| **Description:** | **Joya™ Smart_Smart+ Android™ 15 Version 3.27.022 Firmware Release** | | |
| **Business Unit:** | Mobile Computers | | |

**Distribution Scope:** ☐ **Internal** ☒ **External – specify:** **Public**

## Joya™ Smart_Smart+ Android™ 15 version 3.27.022.20261006s

### 1. COMPATIBILITY

- **Joya™ Smart_Smart+**

**Joya™ Smart+ is fully supported starting with firmware version 3.22.008.20260318s.**

**To check the firmware version, go to Settings>About phone and read the Build number.**

**To check the Android version, go to Settings>About phone and read the Android version.**

### 2. ENHANCEMENTS

#### 2.1. Security Enhancements

a. Updated Android security patches level at September, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-09-01].

#### 2.2. Miscellaneous Enhancements

a. Updated DL Scanner service to 3.2.0.0-r1.1 version including:
   a. Support for the following scan engine variants (239290)
      i. *"XenonXLR"*

ii. "*XenonXLRColor*"
iii. "*ArgonColor*"
iv. "*ArgonRiskExempt*"

b. Updated SDK add-on to 1.50.4 version.
c. Updated DL Services to 1.50.3 version.
d. Added signature permissions for TeamViewer Datalogic Add-On solution in Android signature permissions allowlist. (239636)
e. Introduced support to new mainboard. (238819)

# 3. CORRECTED DEFECTS

## 3.1. Miscellaneous Corrections

a. Fixed a hardware-related issue that caused a conflict when the device was connected to the PC via USB and inserted in the cradle. (239514)

# 4. KNOWN LIMITATIONS

## 4.1. Miscellaneous

a. Wi-Fi user certificates may be lost upon reboot if they are installed via EMMs. (236657, 237671) Workaround: Install Wi-Fi user certificates manually.
b. During the installation of updated DL resources from the Espresso extension, the message "*Google Play Protect - Recommended app scan*" may appear. (207678)

# 5. FILES

- memor1x_3x_js_gms-user-ota-3.27.022.20261006s.zip [Joya™ Smart_Smart+ Android™ 15 GMS 3.27.022]
- ReleaseNotes_Joya Smart_Smart+-Android 15-v3.27.022.pdf [this document]



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

# 6. OTHER NOTES

## Android Security:

- Android security update September 5, 2026

## Other Dependencies:

- Scan2Deploy Studio 2.6.2 or newer
- Datalogic Android SDK 1.50
- Espresso Extension 3.27.003

## Upgrade methods:

- Scan2Deploy Studio: see the specific *Scan2Deploy* section available in the *Joya™ Smart_Smart+ user manual*.
- Joya™ Smart_Smart+: installing OTA locally via *System Update* option available in *Settings>System*.
- SDK intent
- ADB sideload

# 7. SUPPORT

Datalogic Download area:

Joya Smart & Smart+ - Android - Products - Datalogic Developer Portal

Datalogic Support & Service:

Support and Service - Datalogic



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

# 8. HISTORY

## Joya™ Smart_Smart+ Android™ 15 version 3.27.018.20260727s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at August, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-08-01].

### CORRECTED DEFECTS

None

## Joya™ Smart_Smart+ Android™ 15 version 3.27.017.20260721s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at July, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-07-01].

Miscellaneous Enhancements

- Updated SDK add-on to 1.50.3 version.
- Updated DL Services to 1.50.2 version.
- Updated DL Resources to 1.50.4 version.
- Updated SetupWizardScanner to 1.44.0 version.
- Updated DL Settings to 2.29.1 version.
- Updated Battery Manager to 2.19.2 version.
- Updated Dock Manager to 1.32.0 version.
- Added signature permissions for the MDM solution *TinyMDM* to the Android signature permissions allowlist. (226402)
- Added signature permissions for *MCL* enterprise mobility solution in Android signature permissions allowlist. (228951)



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

### CORRECTED DEFECTS

Wi-Fi Corrections

- Fixed an issue where, in some cases, the device was unable to automatically reconnect to the Wi-Fi network after a restart when there was no Internet connection. (231985)

Miscellaneous Corrections

- Correct the signature permissions for *BlueFletch* software suite in Android signature permissions allowlist.
- An issue has been resolved in which the "*uninstall_blocked_packages*" restriction applied to apps installed via Espresso did not prevent the entire uninstallation of those apps via ADB or when attempting to uninstall their updates. (228845, 228846)
- Fixed an issue where *Datalogic settings* could crash if you opened a submenu, then minimized the app, and then reopened it. (231689)
- Fixed a functional issue with the Expedite Setup MDM enrollment feature. (233526)

## Joya™ Smart_Smart+ Android™ 15 version 3.27.015.20260611s

Firmware version not publicly released

## Joya™ Smart_Smart+ Android™ 15 version 3.27.009.20260508s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at June, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-06-01].

Miscellaneous Enhancements

- Updated the wallpaper for Joya Smart+. (229177)
- Updated DL Scanner service to 3.2.0.0-r1 version including:
    a. Added support to Laetus Pharmacode. (218059)
    b. Added GS1 evaluation in scanning preview. (227381)
- Updated SDK add-on to 1.50.2 version.
- Updated DL Services to 1.50.1 version.
- Updated DL Resources to 1.50.2 version.



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated DevicePolicyManager to 5.7.0 version.
- Updated DL Settings to 2.29.0 version.
- Updated Battery Manager to 2.19.1 version.

### CORRECTED DEFECTS

Wi-Fi Corrections

- Fixed an issue where, on some types of Meraki AP, the device might not support connections to hidden SSIDs. (229200)

Miscellaneous Corrections

- Fixed an issue where Dock Manager displayed the message “Wrong insertion” if the device was suspended on an unpowered dock and then resumed after the dock was powered on. (228779)

## Joya™ Smart_Smart+ Android™ 15 version 3.27.008.20260414s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at May, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-05-01].

Miscellaneous Enhancements

- Updated SDK add-on to 1.50.0 version.
- Updated DL Services to 1.50.0 version.
- Updated DL Resources to 1.50.0 version.
- Updated SetupWizardScanner to 1.43.0 version.
- Updated DL Settings to 2.28.3 version.
- Updated Battery Manager to 2.19.0 version.
- Updated Dock Manager to 1.31.0 version.
- Updated DL Extension (UX Settings) to 0.15.0 version.
- Introduced automatic illumination source setting for scanning preview.
- Introduced ITF-14 as GTIN format for scanner formatting.
- Introduced conversion options from GS1-128.



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Introduced the ability to adjust the illumination intensity of Xenon and Argon scanner module.
- Introduced NFC group settings in DL Settings. (226376)
- Introduced Bluetooth Fast Pair option for fast pair compatible BT devices. (227251)
- Added intent action “com.datalogic.device.intent.action.ship_mode.SHIP_MODE_REQUEST” to enable Ship Mode on the device. (228513)
- Integrated automated I2C recovery mechanism specifically for backlight, battery, and NFC subsystems. (228712)

### CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue where Dock Manager displayed the message “Wrong insertion” after a quick insert-and-extract operation from an unpowered dock. (227227)

## Joya™ Smart_Smart+ Android™ 15 version 3.22.008.20260318s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at April, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-04-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.1-r2 version.
- Updated SDK add-on to 1.49.2 version.
- Updated DL Services to 1.49.3 version.
- Updated DL Resources to 1.49.2 version.
- Updated DL Settings to 2.28.2 version.
- Updated DL Extension (UX Settings) to 0.14.3 version.
- Updated DockManager to 1.30.0 version.
- The battery charge percentage overlay that appeared when the device was inserted in the cradle has been removed. (210784)
- Added signature permissions for BlueFletch software suite to the Android signature permissions allowlist. (225416)



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

## CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that caused the Pose Manager user interface to malfunction when the device was inserted in the cradle. (226008, 226029)
- Fixed an issue that, in rare cases after device startup, caused the Battery Manager to report an incorrect battery temperature value. (227444)

# Joya™ Smart_Smart+ Android™ 15 version 3.22.001.20260211s

## ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at March, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-03-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r9 version.
- Updated SDK add-on to 1.49.0 version.
- Updated DL Services to 1.49.0 version.
- Updated DL Resources to 1.49.0 version.
- Updated SetupWizardScanner to 1.42.1 version.
- Updated DL Settings to 2.28.0 version.
- Updated Scan2Deploy Agent to 2.8.0 version.
- Updated Battery Manager to 2.18.0 version.
- Updated DL Extension (UX Settings) to 0.14.2 version.
- Updated DockManager to 1.29.1 version.
- Disabled hint to extend battery life.
- Introduced support for cradle firmware update policy to enable controlled cradle firmware updates. (217452, 224501)
- Introduced automatic WLAN recovery procedure in case of WLAN subsystem crash. (223219)
- Introduced the ability to customize the position and size of the scanner preview window, as well as the illumination source. (223729, 223730)
- Default display brightness set to 100%. (224531)
- Added signature permissions for the MDM solutions SureMDM, Esper, and Omnissa (also known as AirWatch) to the Android signature permissions allowlist. (224544)



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

### CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue where the Wi-Fi connection would sometimes fail to reconnect when returning to the same coverage area. (223291)
- Fixed an issue that prevented an app from rotating the screen in *REVERSE_PORTRAIT* orientation mode. (223320)

## Joya™ Smart_Smart+ Android™ 15 version 3.16.008.20251216s

### ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at January, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-01-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r6 version including:
  a. Added the ability to send an IME action (virtual keyboard function) at the end of the scanned code in keyboard wedge mode (215174)
- Updated SDK add-on to 1.47.8 version.
- Updated DL Services to 1.47.6 version.
- Updated DL Resources to 1.47.7 version.
- Updated SetupWizardScanner to 1.40.3 version.
- Updated DL Settings to 2.26.5 version.
- Updated Battery Manager to 2.17.3 version.
- Updated Dock Manager to 1.26.0 version.
- Updated DL Extension (UX Settings) to 0.13.0 version.

### CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that made it impossible to decrypt Scan2Deploy V3 barcodes after completing the setup process from the “Hi There” screen. (219513)



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

# Joya™ Smart_Smart+ Android™ 15 version 3.16.004.20251124s

## ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at November, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-11-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0-r2 version including:
  a. Always On status maintained at reboot with pin or password set as lock screen
  b. Added alignment of the scanner camera id to the one specified in the firmware
- Updated SDK add-on to 1.46.14 version.
- Updated DL Services to 1.46.14 version.
- Updated DL Resources to 1.47.3 version.
- Updated SetupWizardScanner to 1.40.3 version.
- Updated DL Settings to 2.26.1 version including display brightness range setting.
- Updated Battery Manager to 2.17.0 version.

## CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that prevented the scanner from functioning correctly in the event of a camera failure. (218768)
- Fixed an issue where the device could no longer detect whether it was in the cradle or not. (216676)
- Fixed an issue where the device sometimes did not vibrate after being placed in the cradle. (216648)
- Fixed an issue that prevented the notification LED from turning on when enabled in the notification settings. (215545)

# Joya™ Smart_Smart+ Android™ 15 version 3.12.009.20251013s

First Production Release



© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.